





HYUNDAI TERRACAN - 4WD

HP 11/2001 - 12/2007

Part and Location	Description	Approx Lift	Part Number	Qty Per Vehicle	
SHOCK ABSORBERS					
	35mm Gas Bulged Shock Absorbers supplied with urethane boot		SA35087GL	2 ea	FRONT
TORSION BARS					
	Increased Rate Torsion Bars Length 1275mm		HYUN004	1 pr	
SHOCK ABSORBERS					
	35mm Gas Bulged Shock Absorbers DO NOT use this shock with STD suspension		SA35637GL	2 ea	REAR
COIL SPRINGS					
	Raised Height Medium Duty Coil Springs	40mm	MIT-201	1 pr	